

Sentinel® R700:

Liquid Insurance for GSHP/ASHP Commissioning

SYSTEM DETAILS		SYMPTOMS	COST OF RECOVERY
Type:	GSHP	No heat output	Specialist cleaning fluid £550
Where:	Midlands UK	No faults with Heat Pump mechanicals	R700 Biocide and Sanitiser £30
Age:	2 years old	On examination thermal fluid degraded	Degraded thermal fluid disposal cost £350
Output:	9 kW heat pump	Blockages in Ground Loop due to bacterial slime	2 Man days labour £400
			Thermal Fluid £240
			Lost reputation £?
			TOTAL TO REPAIR £1570

Sentinel® R700 Sanitiser and Biocide

Eliminate risks associated with system cleanliness: use R700 during initial commissioning.

R700 will efficiently sanitise the thermal fluid circuit preventing performance problems caused by uncontrolled bacteria and fungal growth.



£30

to insure your reputation
USE SENTINEL® R700

SENTINEL
EXPERTS IN ENERGY EFFICIENCY

Sentinel Performance Solutions Ltd | The Heath Business & Technical Park
Runcorn | Cheshire | WA7 4QX | T. 01928 588 330 | F. 01928 588 368

www.sentinel-solutions.net
www.sentinelrenewables.net

Sentinel® is a registered trademark of Sentinel Performance Solutions Ltd. All logos and images are copyright of Sentinel Performance Solutions Ltd. No copying, duplication or reproduction of the images and logos is permitted without permission from Sentinel Performance Solutions Ltd.